

EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	0	("vehicleand(tubularsamesteel)and(castsamealuminum").PN.	US-PGPUB;USPAT	OR	OFF	2010/01/31 21:22
S2	234	vehicle and (tubular same steel) and (cast same aluminum)	US-PGPUB;USPAT	OR	OFF	2010/01/31 21:22
S3	9	vehicle and (tubular same steel) and (cast same aluminum) and (yield adj strength)	US-PGPUB;USPAT	OR	OFF	2010/01/31 21:24
S4	23	("2305705" "20040091306" "20060151970" "20060290088" "20090066049" "3650552" "3740986" "4720120" "4738458" "5094474" "5362090" "5381849" "5556119" "5662349" "6070445" "6098437" "6216763" "6231062" "6308970" "6308972" "6311996" "6572126" "6705627").PN.	US-PGPUB;USPAT	OR	OFF	2010/01/31 21:28
S5	228	("1020991" "1703037" "1822197" "1901176" "1977567" "2202665" "2584366" "2757028" "2939720" "3114030" "3118049" "3125493" "3162940" "3208136" "3210102" "3237362" "3467414" "3473359" "3477869" "3551990" "3560244" "3578358" "3709772" "3766633" "3768837" "3774952" "3854030" "3864908" "3867824" "3885821" "3899300" "3909045" "3916504" "3981688" "4016950" "4031699" "4032170" "4077458" "4091648" "4123902" "4124732" "4256253" "4257155" "4269438" "4325647" "4396213" "4442586" "4495397"	US-PGPUB;USPAT;USOCR	OR	OFF	2010/01/31 21:50

"4497428" | "4504714" |
 "4513188" | "4547641" |
 "4636106" | "4637628" |
 "4657795" | "4677271" |
 "4721407" | "4750757" |
 "4798396" | "4804819" |
 "4826346" | "4828285" |
 "4850607" | "4850621" |
 "4900048" | "4900049" |
 "4900050" | "4902048" |
 "4902049" | "4902160" |
 "4902458" | "4964651" |
 "5009448" | "5013514" |
 "5026090" | "5060961" |
 "5073693" | "5076601" |
 "5080385" | "5102156" |
 "5143669" | "5158733" |
 "5160682" | "5163603" |
 "5168142" | "5169171" |
 "5188384" | "5277448" |
 "5283413" | "5322317" |
 "5333775" | "5382034" |
 "5411287" | "5489111" |
 "5507515" | "5511813" |
 "5516129" | "5544406" |
 "5556081" | "5607177" |
 "5620198" | "5662348" |
 "5662349" | "5720092" |
 "5813264" | "5833254" |
 "5853187" | "5890287" |
 "5937496" | "6010155" |
 "6095126" | "6104012" |
 "6113171" | "6139044" |
 "6149181" | "6244088" |
 "6361244" | "6421913" |
 "6427309" | "6428031" |
 "6460250" | "6474534" |
 "6578864" | "D373557" |
 "D379343").PN. OR ("D424989"
 | "D427118" | "D470085").PN.
 OR ("2003/0038453" |
 "2004/0091306" |
 "2009/0134594" | "4206598" |
 "5338057" | "5613794" |
 "6086162" | "6311996" |
 "6464240" | "6654995" |
 "6846001").URPN.

S6	458	"0868524" "1020991" "1332563" "1703037" "1822197" "1889795" "1901176" "1977567" "2006139" "2168631" "2202665" "2233471" "2322587" "2434080" "2463883" "2543087" "2545930" "2584366" "2741498" "2757028" "2825587" "2939720" "3114030" "3118049" "3124874" "3125493" "3162940" "3208136" "3210102" "3237362" "3269743" "3466738" "3467414" "3473359" "3477869" "3514134" "3551990" "3560244" "3578358" "3589873" "3709772" "3734684" "3737284" "3745191" "3766633" "3768837" "3774952" "3784235" "3817562" "3847694" "3854030" "3864908" "3867824" "3885821" "3899300" "3909045" "3916504" "3940168" "3981688" "4016950" "4031699" "4032170" "4077458" "4091648" "4123902" "4124732" "4256253" "4257155" "4269438" "4325647" "4396213" "4442586" "4495397" "4497428" "4504714" "4513188" "4547641" "4572022" "4636106" "4637628" "4657795" "4677271" "4721407" "4750757" "4798396" "4804819" "4826346" "4828285" "4850607" "4850621" "4900048" "4900049" "4900050" "4902048" "4902049" "4902160" "4902458" "4964651" "4991871" "5009448" "5013514" "5026090" "5060961" "5073693" "5076601" "5080385" "5102156" "5143669" "5158733" "5160682" "5163603" "5168142"	US- PGPUB; USPAT; USOCR	OR	OFF	2010/01/31 22:03
----	-----	--	----------------------------------	----	-----	---------------------

		"5169171" "5188384" "5209541" "5277448" "5283413" "5314204" "5322317" "5333775" "5338080" "5382034" "5411287" "5489111" "5507515").PN. OR ("5511813" "5516129" "5544406" "5556081" "5607177" "5613794" "5620198" "5662348" "5662349" "5720092" "5794398" "5813264" "5833254" "5839777" "5853187" "5890287" "5937496" "5954362" "6010155" "6059314" "6068296" "6086162" "6095126" "6102605" "6104012" "6113171" "6116680" "6139044" "6148581" "6149181" "6152468" "6183013" "6216509" "6244088" "6276740" "6282790" "6290082" "6308412" "6346684" "6361244" "6408515" "6421913" "6427309" "6428031" "6460250" "6474534" "6505389" "6578864" "6623067" "6654995" "6668457" "6688803" "6701763" "6702308" "6742258" "6898923" "6922882" "7044565" "7053330" "7204498" "D373557" "D379343" "D424989" "D427118" "D470085").PN. OR ("2003/0038453" "2004/0091306" "2009/0134594" "3208136" "3210102" "3909045" "4206598" "4257155" "4269438" "5338057" "5613794" "6086162" "6311996" "6464240" "6654995" "6846001" "6935657" "7175204" "7399942" "7520516").URPN.				
S7	234	vehicle and (tubular same steel) and (cast same aluminum)	US- PGPUB; USPAT	OR	OFF	2010/01/31 22:03

S8	228	("1020991" "1703037" "1822197" "1901176" "1977567" "2202665" "2584366" "2757028" "2939720" "3114030" "3118049" "3125493" "3162940" "3208136" "3210102" "3237362" "3467414" "3473359" "3477869" "3551990" "3560244" "3578358" "3709772" "3766633" "3768837" "3774952" "3854030" "3864908" "3867824" "3885821" "3899300" "3909045" "3916504" "3981688" "4016950" "4031699" "4032170" "4077458" "4091648" "4123902" "4124732" "4256253" "4257155" "4269438" "4325647" "4396213" "4442586" "4495397" "4497428" "4504714" "4513188" "4547641" "4636106" "4637628" "4657795" "4677271" "4721407" "4750757" "4798396" "4804819" "4826346" "4828285" "4850607" "4850621" "4900048" "4900049" "4900050" "4902048" "4902049" "4902160" "4902458" "4964651" "5009448" "5013514" "5026090" "5060961" "5073693" "5076601" "5080385" "5102156" "5143669" "5158733" "5160682" "5163603" "5168142" "5169171" "5188384" "5277448" "5283413" "5322317" "5333775" "5382034" "5411287" "5489111" "5507515" "5511813" "5516129" "5544406" "5556081" "5607177" "5620198" "5662348" "5662349" "5720092" "5813264" "5833254" "5853187" "5890287" "5937496" "6010155" "6095126" "6104012"	US- PGPUB; USPAT; USOCR	OR	OFF	2010/01/31 22:03
----	-----	---	----------------------------------	----	-----	---------------------

		"6113171" "6139044" "6149181" "6244088" "6361244" "6421913" "6427309" "6428031" "6460250" "6474534" "6578864" "D373557" "D379343").PN. OR ("D424989" "D427118" "D470085").PN. OR ("2003/0038453" "2004/0091306" "2009/0134594" "4206598" "5338057" "5613794" "6086162" "6311996" "6464240" "6654995" "6846001").URPN.				
S9	226	S6 not S7 not S8	US- PGPUB; USPAT; USOCR	OR	OFF	2010/01/31 22:03
S10	2553	vehicle and (tubular same steel) and aluminum	US- PGPUB; USPAT	OR	OFF	2010/01/31 22:15
S11	3290	((280/781) or (280/93.511) or (280/93.512) or (280/124.135) or (280/124.134) or (280/752) or (180/274)).CCL.S.	US- PGPUB; USPAT	OR	OFF	2010/01/31 22:34
S12	60	S11 and vehicle and steel and (cast same aluminum)	US- PGPUB; USPAT	OR	OFF	2010/01/31 22:35
S13	213	S11 and vehicle and steel and aluminum	US- PGPUB; USPAT	OR	OFF	2010/01/31 22:37

7/ 6/ 10 7:46:50 AM

C:\Documents and Settings\TTo\My Documents\EAST\Workspaces\10576377.wsp